

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

202  
SE  
1/4-1/2  
0.331 mi.  
1749 ft.

TRUMP VILLAGE SEC 4 INC  
2940 WEST 5TH ST  
BROOKLYN, NY 11224

NY UST  
NY AST  
NY Spills  
U003127808  
N/A

Relative:  
Higher

UST:

Actual:  
4 ft.

Name: TRUMP VILLAGE SEC 4 INC  
Address: 2940 WEST 5TH ST  
City,State,Zip: BROOKLYN, NY 11224  
Id/Status: 2-277258 / Active  
Program Type: PBS  
Region: STATE  
DEC Region: 2  
Expiration Date: 07/10/2022  
UTM X: 586923.36260  
UTM Y: 4492336.84408  
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 11973  
Affiliation Type: Facility Owner  
Company Name: TRUMP VILLAGE SEC 4 INC  
Contact Type: GENERAL MANAGER  
Contact Name: IGOR OBERMAN  
Address1: 2940 WEST 5TH ST  
Address2: Not reported  
City: BROOKLYN  
State: NY  
Zip Code: 11224  
Country Code: 001  
Phone: (718) 946-4800  
EMail: Not reported  
Fax Number: Not reported  
Modified By: MFLEONAR  
Date Last Modified: 2017-07-20

Site Id: 11973  
Affiliation Type: Mail Contact  
Company Name: TRUMP VILLAGE SEC 4 INC  
Contact Type: Not reported  
Contact Name: IGOR OBERMAN  
Address1: 2928 WEST 5TH ST  
Address2: MGMT OFF  
City: BROOKLYN  
State: NY  
Zip Code: 11224  
Country Code: 001  
Phone: (718) 948-4800  
EMail: IGOR@TRUMP4WEST.COM  
Fax Number: Not reported  
Modified By: MFLEONAR  
Date Last Modified: 2017-07-20

Site Id: 11973  
Affiliation Type: Facility Operator  
Company Name: TRUMP VILLAGE SEC 4 INC  
Contact Type: Not reported  
Contact Name: JULIO SALDANA  
Address1: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Address2: Not reported  
City: Not reported  
State: NN  
Zip Code: Not reported  
Country Code: 999  
Phone: (718) 946-4800  
EMail: Not reported  
Fax Number: Not reported  
Modified By: MFLEONAR  
Date Last Modified: 2017-07-20

Site Id: 11973  
Affiliation Type: Emergency Contact  
Company Name: TRUMP VILLAGE SEC 4 INC  
Contact Type: Not reported  
Contact Name: JULIO SALDANA  
Address1: Not reported  
Address2: Not reported  
City: Not reported  
State: NN  
Zip Code: Not reported  
Country Code: 999  
Phone: (718) 946-4800  
EMail: Not reported  
Fax Number: Not reported  
Modified By: MFLEONAR  
Date Last Modified: 2017-07-20

Tank Info:

Tank Number: 001  
Tank ID: 54905  
Tank Status: Closed - Removed  
Material Name: Closed - Removed  
Capacity Gallons: 35000  
Install Date: 12/01/1963  
Date Tank Closed: 12/01/2009  
Registered: True  
Tank Location: Underground  
Tank Type: Steel/carbon steel  
Material Code: 0001  
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 14  
Date Test: 08/11/2008  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: MFLEONAR  
Last Modified: 07/20/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)  
H00 - Tank Leak Detection - None  
L09 - Piping Leak Detection - Exempt Suction Piping  
A00 - Tank Internal Protection - None  
B01 - Tank External Protection - Painted/Asphalt Coating  
D01 - Pipe Type - Steel/Carbon Steel/Iron  
F01 - Pipe External Protection - Painted/Asphalt Coating  
C03 - Pipe Location - Aboveground/Underground Combination

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

G00 - Tank Secondary Containment - None  
J02 - Dispenser - Suction Dispenser  
I05 - Overfill - Vent Whistle

Tank Number: 002  
Tank ID: 54906  
Tank Status: Closed - Removed  
Material Name: Closed - Removed  
Capacity Gallons: 35000  
Install Date: 12/01/1963  
Date Tank Closed: 12/01/2009  
Registered: True  
Tank Location: Underground  
Tank Type: Steel/carbon steel  
Material Code: 0001  
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: 14  
Date Test: 08/11/2008  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: MFLEONAR  
Last Modified: 07/20/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)  
H00 - Tank Leak Detection - None  
L09 - Piping Leak Detection - Exempt Suction Piping  
A00 - Tank Internal Protection - None  
B01 - Tank External Protection - Painted/Asphalt Coating  
D01 - Pipe Type - Steel/Carbon Steel/Iron  
F01 - Pipe External Protection - Painted/Asphalt Coating  
C03 - Pipe Location - Aboveground/Underground Combination  
G00 - Tank Secondary Containment - None  
J02 - Dispenser - Suction Dispenser  
I05 - Overfill - Vent Whistle

AST:

Name: TRUMP VILLAGE SEC 4 INC  
Address: 2940 WEST 5TH ST  
City,State,Zip: BROOKLYN, NY 11224  
Region: STATE  
DEC Region: 2  
Site Status: Active  
Facility Id: 2-277258  
Program Type: PBS  
UTM X: 586923.36260  
UTM Y: 4492336.84408  
Expiration Date: 07/10/2022  
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 11973  
Affiliation Type: Facility Owner  
Company Name: TRUMP VILLAGE SEC 4 INC  
Contact Type: GENERAL MANAGER  
Contact Name: IGOR OBERMAN  
Address1: 2940 WEST 5TH ST  
Address2: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

City: BROOKLYN  
State: NY  
Zip Code: 11224  
Country Code: 001  
Phone: (718) 946-4800  
EMail: Not reported  
Fax Number: Not reported  
Modified By: MFLEONAR  
Date Last Modified: 2017-07-20

Site Id: 11973  
Affiliation Type: Mail Contact  
Company Name: TRUMP VILLAGE SEC 4 INC  
Contact Type: Not reported  
Contact Name: IGOR OBERMAN  
Address1: 2928 WEST 5TH ST  
Address2: MGMT OFF  
City: BROOKLYN  
State: NY  
Zip Code: 11224  
Country Code: 001  
Phone: (718) 948-4800  
EMail: IGOR@TRUMP4WEST.COM  
Fax Number: Not reported  
Modified By: MFLEONAR  
Date Last Modified: 2017-07-20

Site Id: 11973  
Affiliation Type: Facility Operator  
Company Name: TRUMP VILLAGE SEC 4 INC  
Contact Type: Not reported  
Contact Name: JULIO SALDANA  
Address1: Not reported  
Address2: Not reported  
City: Not reported  
State: NN  
Zip Code: Not reported  
Country Code: 999  
Phone: (718) 946-4800  
EMail: Not reported  
Fax Number: Not reported  
Modified By: MFLEONAR  
Date Last Modified: 2017-07-20

Site Id: 11973  
Affiliation Type: Emergency Contact  
Company Name: TRUMP VILLAGE SEC 4 INC  
Contact Type: Not reported  
Contact Name: JULIO SALDANA  
Address1: Not reported  
Address2: Not reported  
City: Not reported  
State: NN  
Zip Code: Not reported  
Country Code: 999  
Phone: (718) 946-4800  
EMail: Not reported  
Fax Number: Not reported  
Modified By: MFLEONAR

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Date Last Modified: 2017-07-20

Tank Info:

Tank Number: 01  
Tank Id: 249828

Equipment Records:

A00 - Tank Internal Protection - None  
B01 - Tank External Protection - Painted/Asphalt Coating  
D01 - Pipe Type - Steel/Carbon Steel/Iron  
F01 - Pipe External Protection - Painted/Asphalt Coating  
G02 - Tank Secondary Containment - Vault (w/access)  
I05 - Overfill - Vent Whistle  
C01 - Pipe Location - Aboveground  
J05 - Dispenser - On Site Heating System (Supply/Return)  
H05 - Tank Leak Detection - In-Tank System (ATG)  
E00 - Piping Secondary Containment - None  
I02 - Overfill - High Level Alarm  
K01 - Spill Prevention - Catch Basin  
L09 - Piping Leak Detection - Exempt Suction Piping  
Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on

impervious barrier, allowing visual indication of leaks.

Tank Type: Steel/Carbon Steel/Iron  
Tank Status: In Service  
Pipe Model: Not reported  
Install Date: 12/01/2009  
Capacity Gallons: 13500  
Tightness Test Method: -  
Date Test: Not reported  
Next Test Date: Not reported  
Date Tank Closed: Not reported  
Register: True  
Modified By: MFLEONAR  
Last Modified: 07/20/2017  
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 02  
Tank Id: 249829

Equipment Records:

A00 - Tank Internal Protection - None  
B01 - Tank External Protection - Painted/Asphalt Coating  
D01 - Pipe Type - Steel/Carbon Steel/Iron  
F01 - Pipe External Protection - Painted/Asphalt Coating  
G02 - Tank Secondary Containment - Vault (w/access)  
I05 - Overfill - Vent Whistle  
C01 - Pipe Location - Aboveground  
J05 - Dispenser - On Site Heating System (Supply/Return)  
H05 - Tank Leak Detection - In-Tank System (ATG)  
E00 - Piping Secondary Containment - None  
I02 - Overfill - High Level Alarm  
K01 - Spill Prevention - Catch Basin  
L09 - Piping Leak Detection - Exempt Suction Piping  
Tank Location: Aboveground - contact with impervious barrier... Tank bottom rests on  
impervious barrier, allowing visual indication of leaks.

Tank Type: Steel/Carbon Steel/Iron  
Tank Status: In Service  
Pipe Model: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Install Date: 12/01/2009  
Capacity Gallons: 13500  
Tightness Test Method: -  
Date Test: Not reported  
Next Test Date: Not reported  
Date Tank Closed: Not reported  
Register: True  
Modified By: MFLEONAR  
Last Modified: 07/20/2017  
Material Name: #2 fuel oil (on-site consumption)

SPILLS:

Name: RESIDENCE  
Address: 2940 WEST 5TH STREET  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0607564 / 2015-07-14  
Facility ID: 0607564  
Facility Type: ER  
DER Facility ID: 321110

Site ID: 371331  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: D4  
SWIS: 2401  
Spill Date: 2006-10-03  
Investigator: rmpiper  
Referred To: Not reported  
Reported to Dept: 2006-10-03  
CID: 410  
Water Affected: Not reported  
Spill Source: Private Dwelling  
Spill Notifier: Police Department  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2006-10-03  
Spill Record Last Update: 2015-07-14  
Spiller Name: TONY  
Spiller Company: RESIDENCE  
Spiller Address: 2940 WEST 5TH STREET  
Spiller Company: 001  
Contact Name: TONY  
DEC Memo:

"DEC Piper recieved update from DEC Sangesland, as per his conversation w/ PTC Ray, There are two tanks at the propert6y that are UST though mounded w/ soil. Oil was discivered in nearby sump. PTC en route to investigate and pump sump. PTC will update DEC. 11/7/06- DEC spoke w/ PTC, both tanks failed and are now empty. Need to contact Tony Giordano cc: Prestige Plumbing and Heating. 347-392-0616. Ms. Fern Riback ,Trump Village 4 Inc - 2928 West 5th St. Bklyn 11224. DEC Piper psoke w./ Tony, as per him is consulting building and they are determining next step, an environmental contractor has been hired. Need to send CSL letter to: Ms. Fern Riback Trump Village 4 Inc 2928 West 5th St. Brooklyn, NY 11224. 718-946-4964 , 4800 5/1/07- DEC Piper left message for Fern requesting callback, 12/12/07- DECP iper spke w. Rene Lewis of Eastmond. They are pulling both tanks. 35K. Shandel Env. Will be

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

doing remediation Ken Friedman. 914-439-7493. 9/18/08- DECPiper- I spoke with Ken. He will send report shortly. 11/26/08- DECPiper- I left message for Ken requesting callback and report. 7/14/15- Samples collected in former tank location. Based on work to date , this spill is closed. see dec docs for sample results."

Remarks:

"SPILL IS SOME KIND OF HEATING OIL FROM A TANK: LOCATED IN BASEMENT AT THIS RESIDENCE: HOMEOWNER INFORMATION UNKNOWN;"

All Materials:

Site ID: 371331  
Operable Unit ID: 1129094  
Operable Unit: 01  
Material ID: 2118756  
Material Code: 0001A  
Material Name: #2 fuel oil  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: Not reported  
  
Units: G  
Recovered: .00  
Oxygenate: Not reported